

Decal Installation

Installation Conditions



Get Ready...

...Get Set...

Get Your Tools



Some tools you will need:

- Pen or Pencil
- Scissors
- Squeegee
- Masking Tape
- Measuring Tape
- Razor Blade
- Surface Prep Fluids including Isopropyl Rubbing Alcohol
- Heat Gun

Clean Surface

Clean the surface with 70% Isopropyl Rubbing Alcohol and Fresh paper towels.



Align Decal



Mark decal for alignment points. Use masking tape and tape measure to position before placement.



...Go!

Apply tape to center of decal to act as hinge. Peel & remove wax backing from side 1. Remove backing side 1 with scissors. Use squeegee to firmly apply side 1 of the decal.



Peel & remove center tape (if applicable). Remove wax backing from side 2. Use squeegee to firmly apply side 2 of the decal.



Use squeegee to firmly press out decal in all directions, around bumps or corners, and over rivets. Remove transfer film and finish with pin and heat gun, removing air bubbles (if needed).

